

TIL ADDICESS. 43 Norumeta Avenue	SITE ADDRESS:	45 Northfield Avenue
----------------------------------	---------------	----------------------

TOWN/VILLAGE: Dobbs Ferry

DATE: 10/21/2021 TIME: 9:15am

WEATHER: Sunny TEMP. 58° F

WITNESSED BY: Nicholas Shirriah

PERCOLATION TEST HOLE DATA SHEET - STORMWATER MANAGEMENT SYSTEM

HOLE#	CLOCK TIME				PERCOLATION				
				Elapse	Depth to Water From Ground Surface		Water Level in	Soil Rate	
Hole Number	Run No.	Start	Stop	Time (Min.)	Start Inches	Stop Inches	Inches Drop in inches	Min. per inch	Inches per Hour
# _1	1	10:04	10:06	2	22	46	24	0.083	722.89
	2	10:07	10:11	4	22	46	24	0.17	352.94
<u>4</u> ӯ	3	10:12	10:19	7	22	46	24	0.29	206.90
	4	10:19	10:26	7	22	46	24	0.29	206.90
	5								
#_2	1								
" <u>==</u>	2								
<u>4</u> ӯ	3								
	4								
	5								
#_3	1								
" <u>_3</u>	2								
<u>4</u> "Ø	3								
	4								
	5								

Notes:

- 1) Tests to be repeated at the same depth until approximately equal soil rates are obtained at each percolation test hole. All data to be submitted for review.
- 2) Depth measurements to be made from top of hole