

## Site Photographs – Erosion Record



**Photograph 1 – Eroded Western Bank of Wicker's Creek Adjacent to Condominium Complex Parking Lot, Looking North. (Image Dated 10-25-2021)**



**Photograph 2 – Eroded Western Bank of Wicker's Creek Adjacent to Condominium Complex Parking Lot, Looking North. (Image Dated 03-15-2022)**





**Photograph 3 – Eroded Western Bank of Wicker's Creek Abutting Concrete Curb, Looking North.  
(Image Dated 03-15-2022)**



**Photograph 4 – Eroded Western Bank of Wicker's Creek Adjacent to Condominium Complex Parking Lot, Looking North. (Image Dated 03-15-2022)**